GIS REGISTRY INFORMATION

SITE NAME:	US Postal Se	rvice	-Vehicle Ma	ainten	ance Facility						
BRRTS #:	03-13-002442	2				FID	#				
						(if ap	opropri	iate)	:		
COMMERCE #	53714-9999-0	01									
(if appropriate):											
CLOSURE DATE:	September 3,	, 200	4								
STREET ADDRESS:	201 Regas R	oad									
CITY:	Madison										
SOURCE PROPERTY	GPS COORI	DINA	TES	X =	575389	***************************************	Y	= 2	292225		
(meters in WTM91 pro	jection):							4			
CONTAMINATED ME	DIA:	Gro	oundwater		Soil			Both	X		
OFF-SOURCE GW CO	ITANIMATIC	ON >	ES:	Y	'es	X		No			
• IF YES, STREET A	ADDRESS:	3902	Milwaukee	Stree	t, Madison						
 GPS COORDINAT 	ES 2	X = !	575334		100	Y =	2922	20	***************************************		
(meters in WTM91 pro	jection):										
OFF-SOURCE SOIL O	CONTAMINAT	ION	,	Yes		No	X				
>Generic or Site-Spe	cific RCL (SS	RCL	.):				and the state of t				
 IF YES, STREET A 	ADDRESS 1:										
 GPS COORDINAT 	ES	X =				Y =					
(meters in WTM91 pro	jection):										
CONTAMINATION IN	RIGHT OF W	AY:	Yes X			No					
			DOCUMEN	TS N	<u>EEDED</u>						
Closure Letter, and any con	ditional closure le	etter is	ssued								
Copy of most recent deed, i	ncluding legal de	scripti	ion, for all affe	cted pr	operties	***************************************				***************************************	X
Certified survey map or rele	vant portion of th	e reco	orded plat map	(if refe	renced in the legal	descript	ion) for	all aff	ected prop	erties	NA
County Parcel ID number, if	used for county,	for all	affected prop	erties	·						Х
Location Map which outlines a parcels to be located easily (8.5x potable wells within 1200' of the s	14" if paper copy). I	ontamir f ground	nated site bounda dwater standards	aries on s are exc	USGS topographic needed, the map mus	nap or pl st also in	at map in clude the	suffici locati	ient detail to on of all mur	permit the	Х
Detailed Site Map(s) for all wells and potable wells. (8.5x14" way in relation to the source propexceeding ch. NR 720 generic or	', if paper copy) This perty and in relation t	map s	hall also show th	e locatio	n of all contaminated	d public s	streets, hi	ighway	and railroad	d rights-of-	
Tables of Latest Groundwat	er Analytical Res	ults (n	o shading or o	cross-h	atching)						X
Tables of Latest Soil Analyti	ical Results (no s	hading	g or cross-hat	ching)							Х
Isoconcentration map(s), <i>if</i> and extent of groundwater contan								ap sho	uld haye flov	w direction	X
GW: Table of water level ele	evations, with sar	npling	dates, and fre	ee prod	uct noted if prese	ent					X
GW: Latest groundwater flois greater than 20 degrees)	w direction/moni	itoring	well location	map (s	hould be 2 maps	if maxi	imum va	ıriatio	on in flow o	direction	Х
SOIL: Latest horizontal exte	ent of contaminat	ion ex	ceeding gener	ric or S	SRCLs, with one	contou	r				X
Geologic cross-sections, if	required for SI. (8	3.5x14'	' if paper copy)								NA
RP certified statement that I	egal descriptions	are c	omplete and a	ccurate),				allegation of the the the third to the test of the tes		X
Copies of off-source notification	ation letters (if ap	plicab	ole)								X
Letter informing ROW owne	r of residual cont	amina	ition (if applica	able)(pu	ıblic, highway or	railroad	ROW)				X
Copy of (soil or land use) de	ed restriction (s)	or de	ed notice if an	y requi	red as a condition	n of clo	sure				NΑ

BUREAU OF PECFA P.O. Box 8044

Madison, Wisconsin 53708-8044 TDD #: (608) 264-8777

Fax #: (608) 267-1381 Jim Doyle, Governor Cory L. Nettles, Secretary



September 3, 2004

Jammie Williams United States Postal Service Lakeland District Office P.O. Box 370900 Milwaukee, WI 53237-2900

RE: Final Closure

Commerce # 53714-9999-01 WDNR BRRTS # 03-13-002442 US Postal Service-Vehicle Maintenance Facility, 201 Regas Road, Madison

Dear Mr. Williams:

The Wisconsin Department of Commerce (Commerce) has reviewed the request for case closure prepared by your consultant, DPRA Inc, for the site referenced above. Commerce approved case closure in a letter dated August 14, 2000. Case closure was conditional upon receipt of monitoring well abandonment documentation and deed notifications. Commerce appreciates the GIS Registry packet, received on March 23, 2004, in lieu of the deed notifications. The Wisconsin Department of Commerce (Commerce) has received all items required as conditions for closure of the site referenced above. This case is now listed as "closed" on the Commerce database and will be included on the Wisconsin Department of Natural Resources (WDNR) Geographic Information System (GIS) Registry of Closed Remediation Sites to address residual contamination. It is in your best interest to keep all documentation related to the environmental activities that were conducted.

If residual contamination is encountered in the future, it must be managed in accordance with all applicable state and federal regulations. If it is determined that any remaining contamination poses a threat, the case may be reopened and further investigation or remediation may be required.

Timely filing of your final PECFA claim (if applicable) is encouraged. If your claim is not received within 120 days of the date of this letter, interest costs incurred after 60 days of the date of this letter will not be eligible for PECFA reimbursement.

Thank you for your efforts to bring this case to closure. If you have any questions, please contact me in writing at the letterhead address or by telephone at (608) 261-5405.

Sincerely,

Jon Heberer Hydrogeologist, Site Review Section

cc: Matt Schemmel, DPRA Inc.

Case File

1447925 WARRANTY DEED

Regas Company, a Partnership consisting of Sarah Voit, Richard Voit, Gordon Voit, and Arthur Voit, Grantors, of Dane County, Wisconsin, hereby convey and warrant to the United States Postal Service, an independent establishment of the Executive Branch of the Government of the United States, Grantee, of Washington DC, for the sum of \$14,027.50, the following tract of land in Dane County:

Part of the Southeast 1/4 of the Northwest 1/4 of Section 4, Township 7 North, Range 10 East, in the City of Madison, more particularly described as follows: Starting at the intersection of the South quarter section line and the Easterly right of way of Regas Road; thence North 02° 51' 19" West a distance of 759.4 feet to the point of beginning; thence North 02° 51' 19" West a distance of 283.56 feet; thence South 87° 49' 41" West approximately 33 feet and to the centerline of extended Regas Road; thence South 02° 51' 19" East approximately 283.95 feet along the centerline of extended Regas Road; thence North 87° 08' 41" East a distance of 33 feet to the point of beginning, Dane County, Wisconsin, now in the City of Madison, subject to easement to Madison Metropolitan Sewerage District, as contained in instrument recorded on December 3, 1963, as Document No. 1089296.

The Grantors further convey and quitclaim to the Grantee all right, title, and interest of the Grantors in and to any streams, alleys, roads, streets, ways, strips, gores, or railroad rights-of way abutting said land.


In Witness Whereof the Grantors have executed this deed this day of October, 1975.

FEE

REGAS COMPANY, A Partnership consisting of Sarah Voit, Richard Voit, Gordon Voit, and Arthur Voit.

DOCUMENT NO.	FORM 3— QUIT CLAIM		DANE COUNTY REGISTER OF DEEDS
DOCCINAL TO			Doc No 2769244
Gordon G. Voit			1996-06-07 10:08 AM Trans. Fee EXEMPT #155 Rec. Fee 10.00 Pages 1
		("Grantor")	
uit-claims to Regas Company,	U.C. a Wisconsin li	· ·	V33126P 65
	LLC, a Missoille		100220
ompany		("Grantee")	
he following described real estate	in <u>Dane</u>	County,	RETURN TO David B. Billing Solheim Billing & Grimmer, S.C. P.O. Box 1644
State of Wisconsin:			Madison, WI 53701-1644
	Tow D	arcel No : 60-07	10-042-0086-3 & 60-0710-042-0091-2
line of said NW 1/4, 1,26 thence continuing N 7°-2 right-of-way line of Rega feet; thence along the arc bears S 42°-10'-06" W, 3 87°-11'-30" W, along sai This conveyance is exem	77.45 feet; thence it? 77.46° E, 359.87 feet; as Road; thence S 2°-5 of a curve to the right 35.37 feet to the north id north right-of-way, apt from a transfer fee homestead property. Tune April	thence N 87°-15 51'-19" E, along whose radius is right-of-way lin 412.10 feet to th	87°-49°-41" E, along the South 3 feet to the point of beginning; 2-47" E, 372.73 feet to the west said west right-of-way, 328.64 25.00 feet and whose long chord e of Milwaukee Street; thence S the point of beginning. 5. Stats. Section 77.25(15s).
		51. 9	
	(SEAL)	Folder G. V	Most (SEAL)
*	(SEAL)	* Gordon G. V	Most (SEAL)
*	(SEAL)	* Gordon G. Y	/oit(SEAL)
*AUTHENTICA Signature(s) of Gordon G. Voit	(SEAL)	* Gordon G. Y	(SEAL) CKNOWLEDGMENT SCONSIN)) ss.
	(SEAL)	* Gordon G. V	(SEAL) CKNOWLEDGMENT SCONSIN)
Signature(s) of Gordon G. Voit authenricated this 9 hay of	(SEAL)	* Gordon G. V	(SEAL) CKNOWLEDGMENT SCONSIN)
Signature(s) of Gordon G. Voit	(SEAL) ATION t 19 96 AR OF WISCONSIN	* Gordon G. V	(SEAL) CKNOWLEDGMENT SCONSIN)
signature(s) of Gordon G. Void authenticated this Y has of * David B. Billing TITLE: MEMBER STATE BA	(SEAL) ATION t 19 96 AR OF WISCONSIN Wis. Stats.)	* Gordon G. Y	CKNOWLEDGMENT SCONSIN)
authenricated this Y has of * David B. Billing TITLE: MEMBER STATE BA (If not, authorized by §706.06.	(SEAL) ATION t 19 96 AR OF WISCONSIN Wis. Stats.) S DRAFTED BY	* Gordon G. Y	(SEAL) CKNOWLEDGMENT SCONSIN)

STATE BAR OF WISCONSIN FORM No. 3-1982 Solheim Billing & Grimmer, S.C. (Rev. 9/95 DBB/lal)



THE MADIE OF THE PARTY OF THE P

City of Madison - Assessor's Office


Legal Description

(Notice: This description may be abbreviated and is for assessment purposes only. It should not be used to transfer property)

Parcel Number: 071004200920 Address: 3902 Milwaukee St

Lot Number: 0
Block Number: 0


SEC 4, T7N, R10E, PRT SE 1/4 NW 1/4, COMM W 1/4 COR SD SEC, TH N 87 DEG 49 MIN 41 SEC E 1776.1 FT ALG S LN NW 1/4, TH N 02 DEG 51 MIN 19 SEC W 73.04 FT TO POB, TH CONT N SAME BRG 969.92 FT, TH N 87 DEG 49 MIN 41 SEC E 642.7 FT TO W R/W LN N STOUGHTON RD AND PT OF CUR, TH ON CUR TO LEFT, RAD 5840 FT, LC BRS S 04 DEG 07 MIN 19 SEC E 920 FT, TH S 39 DEG 50 MIN 07 SEC W 94.03 FT, TH S 89 DEG 15 MIN 20 SEC W 85.63 FT, TH S 87 DEG 49 MIN 41 SEC W 336.12 FT, TH S 86 DEG 04 MIN 43 SEC W 150.87 FT TO PT OF CUR, TH ON A CUR TO RT, RAD 25 FT, LC BRS N 48 DEG 23 MIN 18 SEC W 35.68 FT TO POB.



MADISON EAST QUAD

1" = 2000'

1N



LEGEND






FIGURE NUMBER: 2	DATE: 12/21/99
SITE PLAN MAP	PROJECT NO.: 9910623 DRAWN BY: ALT
SILE PLAN MAP	DRAWN BY: ALT
UNITED STATES POSTAL SERVICE	REVIEWED BY: GMA
MADISON VMF	APPROXIMATE SCALE: 1" = 100'
MADISON, WISCONSIN	MAXIM DWG. NO .: AUTOCAD/USPSMAD



TABLE 2 CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location MW-1 NR 140												
Date	7/26/95	1/17/96	4/25/96	8/16/98	1/7/99	7/16/99	9/1/99	11/16/99	PAL	R 140 ES		
PARAMETER	.,,20,,5	1/1///0	4123170	0/10/70	1///99	1/10/99	9/1/99	11/10/99	PAL	ES		
Diesel Range Organics (ppb)	< 100	< 100	< 100	< 100				T	LNC	NG		
Gasoline Range Organics (ppb)	<50	<50	<100	< 100	< 18	< 9.0	< 50		NS NS	NS		
VOLATILE ORGANIC COMP			1 < 100	1 < 100	1 < 10	₹ 9.0	< 30	< 8.6	1/2	NS		
Benzene	<0.6	< 0.6	<0.7	T _ 1	ZO 10	z 0 10		T .0.10	ΥΛ=			
Bromodichloromethane	<1.0			<1	< 0.10	< 0.18	< 0.15	<0.18	0.5	5		
Bromoform	<1.0								0.06	0.6		
Bromomethane	<1.0								0.44	1.1		
Carbon tetrachloride	<1.0								1	10		
Chlorodibromomethane	<1.0	***			 				0.5	5		
Chloroethane	<1.0	***							80	60		
Chloroform	<1.0						 			400		
Chloromethane	<1.0	w							0.6	3		
1,2-Dibromo-3-Chloropropane	<1.0								0.3	244-247 (400-444-2400) (400-4400) (400-4400)		
1,2-Dibromoethane	<1.0								0.02	0.2		
1,2-Dichlorobenzene	<1.0								60	0.05		
1,3-Dichlorobenzene	<1.0								125	300		
1,4-Dichlorobenzene	<1.0								15	1250 75		
Dichlorodiflouromethane	<1.0								200			
1,1-Dichloroethane	<1.0							***	85	1000 850		
1,2-Dichloroethane	<1.0								0.5	5		
1,1-Dichloroethylene	<1.0								0.7	7		
Cis-1,2-Dichloroethylene	<1.0								7	70		
Trans-1,2-Dichloroethylene	<1.0								20	100		
1,2-Dichloropropane	<1.0								0.5	5		
1,3-Dichloropropane	<1.0								0.02	0.2		
Ethylbenzene	<1.0	<1.0	< 0.7	<1	< 0.12	< 0.18	< 0.5	<0.18	140	700		
Methylene Chloride	<1.0								0.5	5		
Methyl-tert-butyl-ether	<1.0	< 1.0	< 0.5	<4	< 0.17	< 0.23	<0.3	3.6	12	60		
Naphthalene	<1.0								8	40		
1,1,1,2-Tetrachloroethane	<1.0	w							7	70		
1,1,2,2-Tetrachloroethane	<1.0							wer	0.02	0.2		
Styrene	<1.0								10	100		
Tetrachloroethene	<1.0								0.5	5		
Toluene	<1.0	<1.0	<1	<1	< 0.17	< 0.18	< 0.4	< 0.18	68.6	343		
1,2,4-Trichlorobenzene	<1.0								14	70		
1,1,1-Trichlorethane	<1.0								40	200		
1,1,2-Trichloroethane	<1.0								0.5	5		
Trimethylbenzenes, total	<1.0	<1.0	<1	< 1	< 0.15	< 0.18	< 0.15	< 0.18	96	480		
Vinyl Chloride									0.02	0.2		
Xylenes, total	<1.0		<2	<2	< 0.16	< 0.51	< 0.15	< 0.51	124	620		
METALS (ppb)			····					•				
Lead	<2.0	< 2.0	<3	< 150					1.5	15		

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location	MW-2									NR 140	
Date	7/26/95	1/17/96	4/25/96	8/16/98	1/7/99	716/99	9/1/99	11/16/99	PAL	ES	
PARAMETER						-t	<u> </u>				
Diesel Range Organics (ppb)	110	< 100	< 100	< 100					NS	NS	
Gasoline Range Organics (ppb)					27	< 9	< 50	< 8.6	NS	NS	
VOLATILE ORGANIC COMP	OUNDS (opb)	d	<u> </u>		1	,	1 40.0		110	
Benzene	< 0.6	< 0.6	< 0.7	<1	< 0.10	< 0.18	< 0.15	< 0.18	0.5	5	
Bromodichloromethane	<1.0								0.06	0.6	
Bromoform	<1.0								0.44	1.1	
Bromomethane	<1.0								1	10	
Carbon tetrachloride	<1.0								0.5	5	
Chlorodibromomethane	<1.0								6	60	
Chloroethane	<1.0								80	400	
Chloroform	<1.0					 			0.6	6	
Chloromethane	<1.0								0.3	3	
1,2-Dibromo-3-Chloropropane	<1.0								0.02	0.2	
1,2-Dibromoethane	<1.0								0.02	0.2	
1,2-Dichlorobenzene	<1.0		~~~						60	300	
1,3-Dichlorobenzene	<1.0						****		125	1250	
1,4-Dichlorobenzene	<1.0								15	75	
Dichlorodiflouromethane	<1.0								200		
1,1-Dichloroethane	<1.0								85	1000	
1,2-Dichloroethane	<1.0									850	
1,1-Dichloroethylene	<1.0								0.5 0.7	5 7	
Cis-1,2-Dichloroethylene	<1.0								7		
Trans-1,2-Dichloroethylene	<1.0								20	70	
1,2-Dichloropropane	<1.0								0.5	100	
1,3-Dichloropropane	<1.0								0.02	0.2	
Ethylbenzene	<1.0	<1.0	< 0.7	<1	< 0.12	< 0.18	< 0.5	<0.18	140	700	
Methylene Chloride	<1.0								0.5	5	
Methyl-tert-butyl-ether	<1.0	<1.0	< 0.5	<4	< 0.17	< 0.23	<0.3	5.0	12	60	
Naphthalene	<1.0				70.17			3.0		100000000000000000000000000000000000000	
1,1,1,2-Tetrachloroethane	<1.0								7	40 70	
1,1,2,2-Tetrachloroethane	<1.0		***						0.02		
Styrene	<1.0		W 44 54						10	0.2	
Tetrachloroethene	<1.0								0.5	100	
Toluene	<1.0	<1.0	<1	<1	< 0.17	< 0.18	< 0.4	<0.18	68.6	5	
1,2,4-Trichlorobenzene	<1.0				<u> </u>		< 0.4 	<0.18	14	343	
1,1,1-Trichlorethane	<1.0								40	70	
1,1,2-Trichloroethane	<1.0								0.5	200 5	
Trimethylbenzenes, total	<1.0	<1.0	<1	<1	< 0.15	< 0.18	1.03	< 0.18	96	480	
Vinyl Chloride				~1			1.03		0.02	The state of the s	
Xylenes, total	<1.0		<2	<2	< 0.16	< 0.51	< 0.15	<0.51	124	0.2	
METALS (ppb)					~0.10	<u> </u>	<u> ∼0.13</u>	<u> </u>	144	620	
Lead				7		i	-	T T	1 =		
									1.5	15	

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Date 7/26/95 1/17/96 4/25/96 8/16/98 1/7/99 7/16/99 9/1/99 11/16/99 PAL ES	Sample Location			NR 140							
Diesel Range Organics (ppb) N/A N/A N/A N/A 8400 11,000 NS NS	Date	7/26/95	1/17/96	4/25/96		W-3 1/7/99	7/16/99	9/1/99	11/16/99		
Gasoline Range Organics (ppb) 33,000 39,000 33,000 13,000 9200 4700 6790 12,000 NS NS	PARAMETER					^				<u> </u>	
Gasoline Range Organics (ppb) 33,000 39,000 33,000 13,000 9200 4700 6790 12,000 NS NS	Diesel Range Organics (ppb)	N/A	N/A	N/A	N/A	8400			11 000	NS	NS
VOLATILE ORGANIC COMPOUNDS (ppb)	Gasoline Range Organics (ppb)	33,000					4700	6790			
Benzene				<u> </u>				, 0.30	12,000	110	110
Bromoferm				190	10	28	43	13.8	180	0.5	5
Bromoform	Bromodichloromethane									4	_
Bromomethane						 	 	 	 	4	
Carbon tetrachloride	Bromomethane	ļ					 	 	 		
Chlorodibromomethane	Carbon tetrachloride	()————————————————————————————————————				 	 		<u> </u>		
Chloroform	Chlorodibromomethane							 	 		F-907-644-950-950-950-950-950-950-950-950-950-950
Chlorofrom	Chloroethane							 	İ	-	200000000000000000000000000000000000000
Chloromethane	Chloroform							 	 		_
1,2-Dibromo-3-Chloropropane <25	Chloromethane					l				 	
1,2-Dichlorobenzene	1,2-Dibromo-3-Chloropropane							 	 		7000 CO.
1,3-Dichlorobenzene <25			~~-							Ų	
1,3-Dichlorobenzene	1,2-Dichlorobenzene	<25						 		-	
1,4-Dichlorobenzene	1,3-Dichlorobenzene	<25							1		
Dichlorodiflouromethane	1,4-Dichlorobenzene	<25						 			2000 A CONTRACTOR OF THE PROPERTY OF THE PROPE
1,1-Dichloroethane	Dichlorodiflouromethane	<25	~						ļ		
1,2-Dichloroethane	1,1-Dichloroethane	<25							 	-	
1,1-Dichloroethylene	1,2-Dichloroethane				~~~				 		
Cis-1,2-Dichloroethylene <25 7 70 Trans-1,2-Dichloroethylene <25		<25									
Trans-1,2-Dichloroethylene <25 20 100 1,2-Dichloropropane <25	Cis-1,2-Dichloroethylene	<25							T	1	
1,2-Dichloropropane		<25								1	
1,3-Dichloropropane	1,2-Dichloropropane	<25								-	
Ethylbenzene 500 270 170 43 43 25 54 110 140 700 Methylene Chloride <25	1,3-Dichloropropane	<25									A1000-000000000000000000000000000000000
Methylene Chloride <25 0.5 5 Methyl-tert-butyl-ether <25	Ethylbenzene	500	270	170	43	43	25	54	110		
Methyl-tert-butyl-ether <25 <25 <50 <20 <1.2 <1.5 <2.3 12 60 Naphthalene <25		<25			·				 		
Naphthalene <25	Methyl-tert-butyl-ether	<25	< 25	< 50	< 20		<1.2	<1.5	<2.3		
1,1,1,2-Tetrachloroethane <25		<25									
1,1,2,2-Tetrachloroethane <25		<25	***								THE PROPERTY OF THE PARTY OF TH
Styrene <25 10 100 Tetrachloroethene <25	1,1,2,2-Tetrachloroethane	<25	~~					***		<u> </u>	
Tetrachloroethene <25 0.5 5 Toluene 810 400 190 40 16 2.3 10.4 33 68.6 343 1,2,4-Trichlorobenzene <25		<25			***		***				
Toluene 810 400 190 40 16 2.3 10.4 33 68.6 343 1,2,4-Trichlorobenzene <25		<25									-
1,2,4-Trichlorobenzene <25		810	400	190	40	16	2.3	10.4	33		Pro-06-07-07-07-08-07-07-07-07-07-07-07-07-07-07-07-07-07-
1,1,1-Trichlorethane <25											
1,1,2-Trichloroethane <25		<25									
Trimethylbenzenes, total 4380 4900 5700 2580 1530 650 1520 2110 96 480 Vinyl Chloride 0.02 0.2 Xylenes, total <25		<25									
Vinyl Chloride 0.02 0.2 Xylenes, total <25		4380	4900	5700	2580	1530	650	1520	2110		-
Xylenes, total <25 14,000 1800 1100 410 844 1400 124 620	ļ										1
	Xylenes, total	<25		14,000	1800	1100	410	844	1400		-
METALS (ppb)	METALS (ppb)						**************************************				
Lead <2.0 <2.0 1.5 15	Lead	< 2.0	< 2.0							1.5	15

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard



TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location				MW	V-4				NE	R 140
Date	7/26/95	1/17/96	4/25/96	8/16/98	1/7/99	7/16/99	9/1/99	11/16/99	PAL	ES
PARAMETER									4	
Diesel Range Organics (ppb)									NS	NS
Gasoline Range Organics (ppb)	720	990	750	< 100	30	200	< 50	20	NS	NS
VOLATILE ORGANIC COMPO	OUNDS (pr	ob)			<u> </u>	'				1
Benzene	< 0.6	< 0.6	< 0.7	<1	< 0.10	0.24	< 0.15	< 0.18	0.5	5
Bromodichloromethane	<1.0								0.06	0.6
Bromoform	<1.0		***						0.44	1.1
Bromomethane	<1.0								1	10
Carbon tetrachloride	<1.0							 	0.5	5
Chlorodibromomethane	<1.0						 		6	60
Chloroethane	<1.0						l		80	400
Chloroform	<1.0								0.6	6
Chloromethane	<1.0		***						0.3	3
1,2-Dibromo-3-Chloropropane	<1.0								0.02	0.2
1,2-Dibromoethane	<1.0								0.005	0.05
1,2-Dichlorobenzene	<1.0								60	300
1,3-Dichlorobenzene	<1.0								125	1250
1,4-Dichlorobenzene	<1.0								15	75
Dichlorodiflouromethane	<1.0	~~~							200	1000
1,1-Dichloroethane	<1.0								85	850
1,2-Dichloroethane	<1.0								0.5	5
1,1-Dichloroethylene	<1.0								0.7	7
Cis-1,2-Dichloroethylene	<1.0	~							7	70
Trans-1,2-Dichloroethylene	<1.0								20	100
1,2-Dichloropropane	<1.0								0.5	5
1,3-Dichloropropane	<1.0	***							0.02	0.2
Ethylbenzene	43	9.4	9.6	<1.0	< 0.12	42	< 0.5	< 0.18	140	700
Methylene Chloride	<1.0								0.5	5
Methyl-tert-butyl-ether	<1.0	<1.0	< 0.5	<4	< 0.17	< 0.23	< 0.3	4.3	12	60
Naphthalene	<1.0	***							8	40
1,1,1,2-Tetrachloroethane	<1.0								7	70
1,1,2,2-Tetrachloroethane	<1.0								0.02	0.2
Styrene	<1.0								10	100
Tetrachloroethene	<1.0				***				0.5	5
Toluene	1.8	<1.0	<1.0	<1.0	< 0.17	< 0.18	< 0.4	< 0.18	68.6	343
1,2,4-Trichlorobenzene	<1.0								14	70
1,1,1-Trichlorethane	<1.0								40	200
1,1,2-Trichloroethane	<1.0								0.5	5
Trimethylbenzenes, total	34	118	81	<1.0	< 0.15	2.6	< 0.15	< 0.18	96	480
Vinyl Chloride		***				70 at 100			0.02	0.2
Xylenes, total	<1.0		25	<2	< 0.16	26	< 0.15	< 0.51	124	620
METALS (ppb)										
Lead	< 2.0	< 2.0	<3	< 150					1.5	15

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard --- = Not Analyzed

TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location	MW-5								NR 140	
Date	7/26/95	1/17/96	4/25/96	8/16/98	1/7/99	7/16/99	9/1/99	11/16/99	PAL	ES
PARAMETER									Л	
Diesel Range Organics (ppb)	< 100	< 100	< 100	< 110	80	180		89	NS	NS
Gasoline Range Organics (ppb)					<18	<9	< 50	12	NS	NS
VOLATILE ORGANIC COMPO	OUNDS (p	pb)			<u> </u>		,		110	110
Benzene	< 0.6	< 0.6	< 0.7	<1	< 0.10	< 0.18	< 0.15	< 0.18	0.5	5
Bromodichloromethane	<1.0								0.06	0.6
Bromoform	<1.0								0.44	1.1
Bromomethane	<1.0				 				1	10
Carbon tetrachloride	<1.0							 	0.5	5
Chlorodibromomethane	<1.0								6	60
Chloroethane	<1.0							 	80	400
Chloroform	<1.0			 		T			0.6	6
Chloromethane	<1.0		 						0.3	3
1,2-Dibromo-3-Chloropropane	<1.0								0.02	0.2
1,2-Dibromoethane	<1.0					 			0.02	0.05
1,2-Dichlorobenzene	<1.0					 			60	300
1,3-Dichlorobenzene	<1.0								125	1250
1,4-Dichlorobenzene	<1.0								15	75
Dichlorodiflouromethane	<1.0								200	-
1,1-Dichloroethane	<1.0								85	1000 850
1,2-Dichloroethane	<1.0								0.5	5
1,1-Dichloroethylene	<1.0									7
Cis-1,2-Dichloroethylene	<1.0								7	70
Trans-1,2-Dichloroethylene	<1.0								20	100
1,2-Dichloropropane	<1.0								0.5	5
1,3-Dichloropropane	<1.0							***	0.02	0.2
Ethylbenzene	<1.0	<1.0	< 0.7	<1	< 0.12	< 0.18	<0.5	< 0.18	140	700
Methylene Chloride	<1.0								0.5	5
Methyl-tert-butyl-ether	<1.0	<1.0	< 0.5	<4	< 0.17	< 0.23	<0.3	7.5	12	-
Naphthalene	<1.0				<u> </u>				8	60 40
1,1,1,2-Tetrachloroethane	<1.0								7	70
1,1,2,2-Tetrachloroethane	<1.0								0.02	0.2
Styrene	<1.0								10	
Tetrachloroethene	<1.0						***		0.5	100 5
Toluene	<1.0	<1.0	<1	1.6	< 0.17	< 0.18	< 0.4	<0.18	68.6	
1,2,4-Trichlorobenzene	<1.0						~0.4	< U.18	14	343 70
1,1,1-Trichlorethane	<1.0								40	
1,1,2-Trichloroethane	<1.0							***		200 5
Trimethylbenzenes, total	<1.0	<1.0	<1	<1	< 0.15	< 0.18	< 0.15		0.5	
Vinyl Chloride						<u> </u>		<0.18	96	480
Xylenes, total	<1.0		25	<2	< 0.16		 -0.15	 -0.51	0.02	0.2
METALS (ppb)	<u> </u>				~0.10	< 0.51	< 0.15	< 0.51	124	620
Lead	T					T		I		
									1.5	15

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location		NR 140							
Date	1/4/96	4/25/96	6/16/98	MW-6 2/11/99	7/16/99	9/1/99	11/16/99	PAL	ES
PARAMETER	-		<u> </u>	<u> </u>	1			<u> </u>	
Diesel Range Organics (ppb)							T	NS	NS
Gasoline Range Organics (ppb)				230	20	< 50	97	NS	NS
VOLATILE ORGANIC COMPOU	UNDS (ppb)	L		1		1 - '	110	110
Benzene	0.7	<0.7	<1	2.5	< 0.18	< 0.15	2.7	0.5	5
Bromodichloromethane								0.06	0.6
Bromoform		 						0.44	1.1
Bromomethane								1	10
Carbon tetrachloride								0.5	5
Chlorodibromomethane						T		6	60
Chloroethane						 	 	80	400
Chloroform								0.6	6
Chloromethane					 		 	0.3	3
1,2-Dibromo-3-Chloropropane								0.02	0.2
1,2-Dibromoethane								0.005	0.05
1,2-Dichlorobenzene								60	300
1,3-Dichlorobenzene								125	1250
1,4-Dichlorobenzene								15	75
Dichlorodiflouromethane								200	1000
1,1-Dichloroethane								85	850
1,2-Dichloroethane								0.5	5
1,1-Dichloroethylene								0.7	7
Cis-1,2-Dichloroethylene								7	70
Trans-1,2-Dichloroethylene								20	100
1,2-Dichloropropane								0.5	5
1,3-Dichloropropane			***					0.02	0.2
Ethylbenzene	<1.0	< 0.7	<1	1.8	< 0.18	< 0.5	0.44	140	700
Methylene Chloride								0.5	5
Methyl-tert-butyl-ether	<1.0	< 0.5	<4	< 0.17	< 0.23	< 0.3	13	12	60
Naphthalene								8	40
1,1,1,2-Tetrachloroethane								7	70
1,1,2,2-Tetrachloroethane						N W 24		0.02	0.2
Styrene				~~~				10	100
Tetrachloroethene								0.5	5
Toluene	3.8	<1	1.4	< 0.17	< 0.18	< 0.4	< 0.18	68.6	343
1,2,4-Trichlorobenzene								14	70
1,1,1-Trichlorethane								40	200
1,1,2-Trichloroethane								0.5	5
Trimethylbenzenes, total	1.8	<1	3.9	13	3.5	0.409	< 0.18	96	480
Vinyl Chloride								0.02	0.2
Xylenes, total		<2	2.3	6.5	< 0.51	0.263	1.7	124	620
METALS (ppb)									
Lead	< 2.0	<3	< 150					1.5	15
									1.0

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

MAXIM TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location				MW-7				NE	R 140
Date	1/4/96	4/25/96	6/16/98	2/11/99	7/16/99	9/1/99	11/16/99	PAL	ES
PARAMETER							4.	A	
Diesel Range Organics (ppb)								NS	NS
Gasoline Range Organics (ppb)		***		34	12	< 50	< 8.6	NS	NS
VOLATILE ORGANIC COMPO	DUNDS (pr	ob)	Laurence de la company de		1			1	
Benzene	95	39	<1	0.54	< 0.18	< 0.15	<0.18	0.5	5
Bromodichloromethane								0.06	0.6
Bromoform								0.44	1.1
Bromomethane								1	10
Carbon tetrachloride								0.5	5
Chlorodibromomethane								6	60
Chloroethane					~~~			80	400
Chloroform						 		0.6	6
Chloromethane								0.3	3
1,2-Dibromo-3-Chloropropane								0.02	0.2
1,2-Dibromoethane								0.005	0.05
1,2-Dichlorobenzene								60	300
1,3-Dichlorobenzene								125	1250
1,4-Dichlorobenzene								15	75
Dichlorodiflouromethane								200	1000
1,1-Dichloroethane				100 Mar 100				85	850
1,2-Dichloroethane								0.5	5
1,1-Dichloroethylene			·					0.7	7
Cis-1,2-Dichloroethylene								7	70
Trans-1,2-Dichloroethylene								20	100
1,2-Dichloropropane								0.5	5
1,3-Dichloropropane								0.02	0.2
Ethylbenzene	4.3	2.1	<1	< 0.12	< 0.18	< 0.5	< 0.18	140	700
Methylene Chloride								0.5	5
Methyl-tert-butyl-ether	5.2	4.0	<4	< 0.17	< 0.23	< 0.3	5.3	12	60
Naphthalene							w- 0	8	40
1,1,1,2-Tetrachloroethane								7	70
1,1,2,2-Tetrachloroethane								0.02	0.2
Styrene								10	100
Tetrachloroethene								0.5	5
Toluene	5.5	<1	<1	< 0.17	< 0.18	< 0.4	< 0.18	68.6	343
1,2,4-Trichlorobenzene						w w		14	70
1,1,1-Trichlorethane								40	200
1,1,2-Trichloroethane								0.5	5
Trimethylbenzenes, total	<1.0	<1	<1	< 0.67	< 0.18	< 0.15	< 0.18	96	480
Vinyl Chloride								0.02	0.2
Xylenes, total	<u> </u>	5.3	<2	< 0.16	< 0.51	< 0.15	< 0.51	124	620
METALS (ppb)									
Lead	<2.0	<3	<150					1.5	15

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

MAXIM TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location	MW-8								140
Date	1/4/96	4/25/96	6/16/98	2/11/99	7/16/99	9/1/99	11/16/99	PAL	ES
PARAMETER									
Diesel Range Organics (ppb)								NS	NS
Gasoline Range Organics (ppb)							< 8.6	NS	NS
VOLATILE ORGANIC COMP	OUNDS (p	pb)				•	A	<u> </u>	
Benzene	0.8	< 0.7	<1				< 0.18	0.5	5
Bromodichloromethane								0.06	0.6
Bromoform							 	0.44	1.1
Bromomethane								1	10
Carbon tetrachloride								0.5	5
Chlorodibromomethane								6	60
Chloroethane								80	400
Chloroform								0.6	6
Chloromethane								0.3	3
1,2-Dibromo-3-Chloropropane								0.02	0.2
1,2-Dibromoethane								0.005	0.05
1,2-Dichlorobenzene				~~=	700 Tab 200			60	300
1,3-Dichlorobenzene								125	1250
1,4-Dichlorobenzene								15	75
Dichlorodiflouromethane								200	1000
1,1-Dichloroethane								85	850
1,2-Dichloroethane								0.5	5
1,1-Dichloroethylene								0.7	7
Cis-1,2-Dichloroethylene								7	70
Trans-1,2-Dichloroethylene								20	100
1,2-Dichloropropane								0.5	5
1,3-Dichloropropane								0.02	0.2
Ethylbenzene	1.8	< 0.7	<1				< 0.18	140	700
Methylene Chloride								0.5	5
Methyl-tert-butyl-ether	<1.0	< 0.5	<4				5.1	12	60
Naphthalene	***							8	40
1,1,1,2-Tetrachloroethane								7	70
1,1,2,2-Tetrachloroethane			****					0.02	0.2
Styrene								10	100
Tetrachloroethene				70 m m		tack time state		0.5	5
Toluene	7.4	<1	<1				<0.18	68.6	343
1,2,4-Trichlorobenzene						***		14	70
1,1,1-Trichlorethane								40	200
1,1,2-Trichloroethane								0.5	5
Trimethylbenzenes, total	1.5	0.9	2.5				< 0.18	96	480
Vinyl Chloride				***				0.02	0.2
Xylenes, total		<2	<2				<0.51	124	620
METALS (ppb)									
Lead	<2.0	<3	<150		***			1.5	15

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

MAXIM PROJECT #9910623										
Sample Location	6/16/00	T	MW-3P				R 140			
Date	6/16/98	1/7/99	7/16/99	9/1/99	11/16/99	PAL	ES			
PARAMETER	7	Ţ								
Diesel Range Organics (ppb)						NS	NS			
Gasoline Range Organics (ppb)	<100	< 18	9	< 50	< 8.6	NS	NS			
VOLATILE ORGANIC COMPO	OUNDS (ppb)									
Benzene	<1	< 0.10	< 0.18	< 0.15	< 0.18	0.5	5			
Bromodichloromethane						0.06	0.6			
Bromoform						0.44	1.1			
Bromomethane						1	10			
Carbon tetrachloride						0.5	5			
Chlorodibromomethane						6	60			
Chloroethane						80	400			
Chloroform						0.6	6			
Chloromethane						0.3	3			
1,2-Dibromo-3-Chloropropane						0.02	0.2			
1,2-Dibromoethane						0.005	0.05			
1,2-Dichlorobenzene						60	300			
1,3-Dichlorobenzene			40 Var ma			125	1250			
1,4-Dichlorobenzene						15	75			
Dichlorodiflouromethane						200	1000			
1,1-Dichloroethane						85	850			
1,2-Dichloroethane						0.5	5			
1,1-Dichloroethylene						0.7	7			
Cis-1,2-Dichloroethylene						7	70			
Trans-1,2-Dichloroethylene						20	100			
1,2-Dichloropropane						0.5	5			
1,3-Dichloropropane						0.02	0.2			
Ethylbenzene	<1	< 0.12	< 0.18	< 0.5	< 0.18	140	700			
Methylene Chloride						0.5	5			
Methyl-tert-butyl-ether	<4	< 0.17	< 0.23	< 0.3	6.1	12	60			
Naphthalene				~~~		8	40			
1,1,1,2-Tetrachloroethane						7	70			
1,1,2,2-Tetrachloroethane						0.02	0.2			
Styrene						10	100			
Tetrachloroethene			~~~			0.5	5			
Toluene	<1	< 0.17	< 0.18	<0.4	< 0.18	68.6	343			
1,2,4-Trichlorobenzene						14	70			
1,1,1-Trichlorethane	***					40	200			
1,1,2-Trichloroethane						0.5	5			
Trimethylbenzenes, total	<1	< 0.15	< 0.18	< 0.15	< 0.18	96	480			
Vinyl Chloride						0.02	0.2			
Xylenes, total	<2	< 0.16	< 0.51	< 0.15	< 0.51	124	620			
METALS (ppb)		0								
Lead	<150					1.5	15			
						1.0	1.0			

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

		ROJECT;		J		
Sample Location	SUMP		RW-1R			R 140
Date	7/14/98	7/16/99	9/1/99	11/16/99	PAL	ES
PARAMETER	1					
Diesel Range Organics (ppb)	72	4300			NS	NS
Gasoline Range Organics (ppb)	<u> </u>	26	1170	73	NS	NS
VOLATILE ORGANIC COMPO	OUNDS (ppb)				•	
Benzene	<1	< 0.18	15.9	0.70	0.5	5
Bromodichloromethane					0.06	0.6
Bromoform					0.44	1.1
Bromomethane					1	10
Carbon tetrachloride					0.5	5
Chlorodibromomethane					6	60
Chloroethane					80	400
Chloroform					0.6	6
Chloromethane					0.3	3
1,2-Dibromo-3-Chloropropane					0.02	0.2
1,2-Dibromoethane					0.005	0.05
1,2-Dichlorobenzene					60	300
1,3-Dichlorobenzene					125	1250
1,4-Dichlorobenzene				*	15	75
Dichlorodiflouromethane					200	1000
1,1-Dichloroethane					85	850
1,2-Dichloroethane					0.5	5
1,1-Dichloroethylene					0.7	7
Cis-1,2-Dichloroethylene					7	70
Trans-1,2-Dichloroethylene					20	100
1,2-Dichloropropane					0.5	5
1,3-Dichloropropane					0.02	0.2
Ethylbenzene	<1	< 0.18	<2.5	< 0.18	140	700
Methylene Chloride					0.5	5
Methyl-tert-butyl-ether	<4	< 0.23	<1.5	8.1	12	60
Naphthalene					8	40
1,1,1,2-Tetrachloroethane					7	70
1,1,2,2-Tetrachloroethane					0.02	0.2
Styrene					10	100
Tetrachloroethene					0.5	5
Toluene	<1	1.2	19.1	0.39	68.6	343
1,2,4-Trichlorobenzene					14	70
1,1,1-Trichlorethane		+			40	200
1,1,2-Trichloroethane					0.5	5
Trimethylbenzenes, total	<1	< 0.18	97.7	7.7	96	480
Vinyl Chloride					0.02	0.2
Xylenes, total	<2	< 0.51	249	24	124	620
METALS (ppb)						
Lead		1.5		[1.5	15
			<u> </u>			

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard



TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location	a 3.7371	~ 4	1		T	7	
Date	2/27/96	6/16/98	2/27/96	MSD-1	Field Blank		VR 140
PARAMETER	2/2//90	0/10/98	2/2//96	6/16/98	7/26/95	PAL	ES
Diesel Range Organics (ppb)			T	1	T	T	
Gasoline Range Organics (ppb)			ļ		< 100	NS	NS
	VENIDO ()	<u> </u>	l	<u> </u>	< 50	NS	NS
VOLATILE ORGANIC COMPO	7	7	1	7	,		
Benzene	<0.6	<1	< 0.6	<1	<0.6	0.5	5
Bromodichloromethane					<1.0	0.06	0.6
Bromoform			<u> </u>		<1.0	0.44	1.1
Bromomethane Carbon tetrachloride					<1.0	1	10
Chlorodibromomethane					<1.0	0.5	5
Chloroethane					<1.0	6	60
Chloroform					<1.0	80	400
Chloromethane					<1.0	0.6	6
					<1.0	0.3	3
1,2-Dibromo-3-Chloropropane					<1.0	0.02	0.2
1,2-Dibromoethane					<1.0	0.005	0.05
1,2-Dichlorobenzene					<1.0	60	300
1,3-Dichlorobenzene					<1.0	125	1250
1,4-Dichlorobenzene					<1.0	15	75
Dichlorodiflouromethane					<1.0	200	1000
1,1-Dichloroethane					<1.0	85	850
1,2-Dichloroethane					<1.0	0.5	5
1,1-Dichloroethylene					<1.0	0.7	7
Cis-1,2-Dichloroethylene					<1.0	7	70
Trans-1,2-Dichloroethylene					<1.0	20	100
1,2-Dichloropropane					<1.0	0.5	5
1,3-Dichloropropane					<1.0	0.02	0.2
Ethylbenzene	< 0.57	<1	< 0.57	<1	<1.0	140	700
Methylene Chloride					<1.0	0.5	5
Methyl-tert-butyl-ether	<1.2	<4	<1.2	<4	<1.0	12	60
Naphthalene					<1.0	8	40
1,1,1,2-Tetrachloroethane					<1.0	7	70
1,1,2,2-Tetrachloroethane					<1.0	0.02	0.2
Styrene					<1.0	10	100
Tetrachloroethene					<1.0	0.5	5
Toluene	<1.0	<1	<1.0	<1	<1.0	68.6	343
1,2,4-Trichlorobenzene					<1.0	14	70
1,1,1-Trichlorethane					<1.0	40	200
1,1,2-Trichloroethane					<1.0	0.5	5
Trimethylbenzenes, total	<1.84	<1	<1.84	<1	<1.0	96	480
Vinyl Chloride					<1.0	0.02	0.2
Xylenes, total	<2.5	<2	< 2.5	<2		124	620
METALS (ppb)							
Lead	< 3	< 150	<3	< 150	< 2.0	1.5	15

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard

TECHNOLOGIES, INC.®

TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER - VOC US POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location			XXXIIVI I I		Blank					
Date	7/26/95	1/5/96	1/17/96	4/25/96	6/16/98	7/14/98	7/16/99	11/16/99		R 140
PARAMETER	1120190	115/70	1/1///	7/43/70	0/10/98	1/14/90	//10/99	11/10/99	PAL	ES
Diesel Range Organics (ppb)			T	T			T*************************************	T.	Lic	1
Gasoline Range Organics (ppb)	< 50		< 50						NS	NS
VOLATILE ORGANIC COMP			1 < 30		l	l		< 8.6	NS	NS
Benzene	< 0.6		-06	1 40 7	T = 1	T	, I .o.ao	1	Т	1
Bromodichloromethane	<1.0	<0.6	<0.6	<0.7	<1	<1	<0.18	< 0.18	0.5	5
Bromoform	<1.0								0.06	0.6
Bromomethane	<1.0								0.44	1.1
Carbon tetrachloride	<1.0								1 0.7	10
Chlorodibromomethane	<1.0							***	0.5	5
Chloroethane	<1.0								6	60
Chloroform	<1.0					 		***	80	400
Chloromoethane	<1.0								0.6	6
1,2-Dibromo-3-Chloropropane	<1.0								0.3	3
1,2-Dibromethane	<1.0								0.02	0.2
1,2-Dichlorobenzene	<1.0							 	60	0.05
1,3-Dichlorobenzene	<1.0									300
1,4-Dichlorobenzene	<1.0								125	1250 75
Dichlorodiflouromethane	<1.0								15	_
1,1-Dichloroethane	<1.0								200 85	1000
1,2-Dichloroethane	<1.0							***	0.5	850
1,1-Dichloroethylene	<1.0								0.7	5 7
Cis-1,2-Dichloroethylene	< 1.0								7	70
Trans-1,2-Dichloroethylene	< 1.0								20	100
1,2-Dichloropropane	< 1.0								0.5	5
1,3-Dichloropropane	<1.0								0.02	0.2
Ethylbenzene	< 1.0	< 1.0	<1.0	<0.7	<1	<1	< 0.18	<0.18	140	700
Methylene Chloride	< 1.0								0.5	5
Methyl-tert-butyl-ether	< 1.0	<1.0	<1.0	< 0.5	<4	<4	< 0.23	9.9	12	60
Naphthalene	< 1.0								8	40
1,1,1,2-Tetrachloroethane	<1.0								7	70
1,1,2,2-Tetrachloroethane	<1.0								0.02	0.2
Styrene	<1.0								10	100
Tetrachloroethene	<1.0								0.5	5
Toluene	< 1.0	<1.0	<1.0	<1	<1	<1	< 0.18	< 0.18	68.6	343
1,2,4-Trichlorobenzene	<1.0								14	70
1,1,1-Trichlorethane	<1.0								40	200
1,1,2-Trichloroethane	<1.0								0.5	5
Trimethylbenzenes, total	<1.0	<1.0	<1.0	<1	3.9	<1	< 0.18	< 0.18	96	480
Vinyl Chloride	<1.0								0.02	0.2
Xylenes, total				<2	<2	<2	< 0.51	< 0.51	124	620
METALS (ppb)				· · · · · · · · · · · · · · · · · · ·	<u></u>					1 7 7 7
Lead				<3	< 150	< 150			1.5	15
					1200	7120			1.0	1.7

Shaded or bold value exceeds WDNR ES or PAL for that parameter.

< = Parameter was not detected and if present is less than the LOD reported.

The inferred extent of groundwater contamination is depicted on Figures 4 & 5.

NS = No established standard



TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER POLYNUCLEAR AROMATIC HYDROCARBONS U.S. POSTAL SERVICE MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location	Sump		RW-1R		M	W-3	N	R140
Date	7/14/98	7/16/99	9/1/99	11/16/99	9/1/99	11/16/99	PAL	ES
POLYNUCLEAR AROMATIC	HYDROC	ARBONS (1	opb)		л		<u> </u>	
Acenaphthene	< 10	<1.5	1.53	< 0.26	23.6	< 0.24	NS	NS
Acenaphthylene	< 10	3.9	< 0.1	< 0.75	<0.1	· 16	NS	NS
Anthracene	< 10	< 0.070	< 0.09	< 0.053	< 0.09	0.81	600	3000
Benzo(a)Anthracene	< 10	0.23	< 0.05	< 0.039	< 0.05	< 0.034	NS	NS
Benzo(a)Pyrene	< 10	< 0.095	< 0.04	< 0.016	< 0.04	< 0.014	0.02	0.2
Benzo(b)Flouranthene	< 10	0.65	0.065	< 0.14	< 0.04	< 0.024	0.02	0.2
Benzo(g,h,i)Perylene	< 10	< 0.37	< 0.06	< 0.053	< 0.06	< 0.047	NS	NS
Benzo(k)Flouranthene	< 10	< 0.27	< 0.06	< 0.027	< 0.06	< 0.024	NS	NS
Chrysene	< 10	1.3	< 0.05	< 0.027	< 0.05	< 0.024	0.02	0.2
Dibenzo(a,h)Anthracene	< 10	< 0.75	< 0.1	< 0.036	< 0.1	< 0.032	NS	NS
Flouranthene	< 10	< 0.22	0.175	< 0.11	0.895	1.0	80	400
Fluorene	< 10	1.1	0.476	< 0.052	6.11	3.3	80	400
Indeno(1,2,3-cd)Pyrene	< 10	< 0.17	< 0.07	< 0.028	< 0.07	< 0.025	NS	NS
1-Methyl Naphthalene		< 1.0	2.25	< 0.18	36.0	59	NS	NS
2-Methyl Naphthalene	< 10	<1.3	3.54	< 0.18	125	110	NS	NS
Naphthalene	< 10	< 2.0	2.89	< 0.034	91.4	110	8	40
Phenanthrene	< 10	< 0.46	< 0.08	< 0.024	< 0.08	1.8	NS	NS
Phenol	26						1200	6000
Pyrene	< 10	0.36	< 0.11	< 0.041	< 0.11	0.48	50	250
Total 8310 List	26	7.54	10.9	< 0.75	283	302.39	NS	NS

Shaded or bold value exceeds WDNR ES or PAL for that parameter

< = Parameter was not detected and if present is less than the limit of detection reported

NS = No established standard

--- = Not analyzed

Monitoring well locations are shown on Figure 2.

The inferred extent of groundwater contamination is depicted in Figures 4 and 5.

NOTE: RW-1R is the replacement recovery well for the sump.



TABLE 2 (CONTINUED) CHEMICAL ANALYSIS OF GROUNDWATER POLYNUCLEAR AROMATIC HYDROCARBONS U.S. POSTAL SERVICE MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM PROJECT #9910623

Sample Location		M	W-5		1	VR140
Date	6/16/98	7/16/99	9/1/99	11/16/99	PAL	ES
POLYNUCLEAR AROMAT	IC HYDRO	CARBONS	(ppb)			
Acenaphthene	<2.2	< 0.29	< 0.1	< 0.68	NS	NS
Acenaphthylene	<1.7	< 0.46	< 0.1	< 0.68	·NS	NS
Anthracene	< 0.056	< 0.014	< 0.09	< 0.48	600	3000
Benzo(a)Anthracene	< 0.11	< 0.025	< 0.05	< 0.035	NS	NS
Benzo(a)Pyrene	< 0.11	< 0.019	< 0.04	< 0.014	0.02	0.2
Benzo(b)Flouranthene	< 0.33	< 0.037	< 0.04	< 0.12	0.02	0.2
Benzo(g,h,i)Perylene	< 0.22	< 0.074	< 0.06	< 0.048	NS	NS
Benzo(k)Flouranthene	< 0.11	< 0.053	< 0.06	< 0.024	NS	NS
Chrysene	< 0.11	< 0.027	< 0.05	< 0.024	0.02	0.2
Dibenzo(a,h)Anthracene	< 0.22	< 0.15	< 0.1	< 0.033	NS	NS
Flouranthene	< 0.33	< 0.044	< 0.06	< 0.095	80	400
Fluorene	< 0.34	< 0.028	< 0.07	< 0.047	80	400
Indeno(1,2,3-cd)Pyrene	< 0.22	< 0.033	< 0.07	< 0.026	NS	NS
1-Methyl Naphthalene		< 0.20	< 0.9	< 0.16	NS	NS
2-Methyl Naphthalene		< 0.26	< 0.8	< 0.16	NS	NS
Naphthalene	<1.7	< 0.39	< 0.08	< 0.30	8	40
Phenanthrene	< 0.22	< 0.029	< 0.08	< 0021	NS	NS
Phenol					1200	6000
Pyrene	< 0.11	< 0.037	< 0.11	< 0.037	50	250
Total 8310 List	<2.2	< 46	<0.9	< 0.68	NS	NS

Shaded or bold value exceeds WDNR ES or PAL for that parameter

< = Parameter was not detected and if present is less than the limit of detection reported

NS = No established standard

--- = Not analyzed

Monitoring well locations are shown on Figure 2.

The inferred extent of groundwater contamination is depicted in Figures 4 and 5.



TABLE 3 NATURAL ATTENUATION MONITORING UNITED STATES POSTAL SERVICE MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM #9910623

		Temperature (°C)	рН	Dissolved Oxygen (ppm)	Oxidation / Reduction Potential (Redox) (mv)	Ferrous Iron (Fe ⁺²) (mg/L)
		Ox solubility and rxn rates are temperature dependant	Difference in pH may indicate biological activity	> 1-2 ppm = aerobic bio-degradation	>-220 mV = most redox rxns >750 = aerobic rxns <750 mV = anaerobic rxns	Presence indicates anaerobic biodegradation
	1/7/99			2.81	,+190	0.0
MW-1	7/16/99	15.9	6.60	3.63	+145	0
141 44 - 1	9/1/99		6.95	2.83	+35	0.0
	11/16/99	14.9	5.98	1.13	+185	0.0
	1/7/99			2.81	+175	0.0
MW-2	7/16/99	16.0	6.59	1.24	+165	0.02
101 00 -2	9/1/99		6.80	0.60	+90	0.2
	11/16/99	15.4	5.98	0.63	+170	0.0
	2/11/99	10.8		0.52	-5	0.0
MW-3	7/16/99	16.3	6.59	0.63	<-50	8.6
101 00 -3	9/1/99		6.90	0.37	<-50	4.5
	11/16/99	15.5	5.9	0.92	-35	5.6
	1/7/99	10.7		0,90	+100	0.1
MW-4	7/16/99	15.0	6.69	0.41	+30	0
M w -4	9/1/99		6.98	0.56	+110	0.0
	11/16/99	15.3	5.97	1.00	+45	0.0
	1/7/99			1.94	+165	0.0
14337.5	7/16/99	18.1	6.72	2.92	+50	0.0
MW-5	9/1/99		7.01	1.35	+120	0.0
	11/16/99	15.4	5.87	0.80	+50	0.0
	2/11/99	10.5	***	1.82	+135	0.0
1007.6	7/16/99	12.6	6.56	0.28	<-50	10
MW-6	9/1/99	***	6.60	0.56	-35	5.5
	11/16/99	14.2	5.79	0.28	-65	4.4
	2/11/99	11.2		0.83	<u>-5</u>	0.0
) (XX / M	7/16/99	13.0	6.51	0.67	<-50	6.6
MW-7	9/1/99		7.01	0.48	<-50	5.0
	11/16/99	14.0	5.78	0.79	-60	4.6
	2/11/99		***			
	7/16/99	*	*	*	*	*
MW-8	9/1/99	*	*	*	*	*
	11/16/99	11.5	5.77	0.41	+5	0.0
	1/7/99	12.3		2.06	+160	0.1
1 (IV) (2D)	7/16/99	16.5	6.67	6.97	+15	0.1
MW-3P	9/1/99		7.10	1.37	+145	0.0
	11/16/99	15.2	5.99	4.89	+160	0.0
	7/16/99	19.1	6.72	2.50	-45	0.0
RW-1R	9/1/99		6.98	2.02	+135	1.0
	11/16/99	16.4	5.76	1.14	+10	0.0

NOTE: Values indicative of anaerobic bio-degradation conditions are highlighted. Redox instrument range is -50 to +1050 mV

rxn = reaction

ppm = parts-per-millionmV = millivolts

* = well not located

°C = degrees Celsius

TABLE 2

SUMMARY OF FIELD DATA AND LABORATORY ANALYSIS RESULTS FROM DIESEL FUEL UNDERGROUND STORAGE TANK

USPS - MADISON VEHICLE MAINTENANCE FACILITY

Sample ID	Location/ Description	Approximate Depth (feet)	PID Reading (instrument units)	DRO (mg/kg)
D-1	North side, west	1 - 3	5	
D-2	South side, west	1 - 3	3	
D-3	West end, south	3	1	
D-4	West end, middle	3	1	
D-5	South side, east	3	< 2	
D-6	North side, east	3	< 2	
D-7	East end, middle	6 - 8	< 2	
D-8	North side, mid-east	6 - 8	< 2	
D-9	South side, mid-east	6 - 8	< 2	
D-10	South side, mid-west	6 - 8	< 2	
D-11	West end, middle	6 - 8	< 2	
D-12	North side, mid-west	6 - 8	< 2	
D-EAST	East wall	8	< 2	< 3.7
D-WEST	West wall and piping	8	< 2	26
D-NORTH	North wall	8	< 2	< 4.2
D-SOUTH	South wall	8	< 2	< 3.9
D-P2	Piping	3	5	130
D-P3	Piping	3 .	< 2	< 3.2
D-P4	Piping	3	5	< 3.5
D-P5	Piping	3	< 2	< 3.9



TABLE 4

UNITED STATES POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY PRE-REMEDIATION SOIL ANALYTICAL DATA

MADISON, WISCONSIN

MAXIM #9910623

Location	SB-1	SB-2	SB-3	SB-4	SB-5	SB-6	SB-7	SB-8	SB-9	SB-10	SB-11	SB-12	SB-13	NR 700
Depth (ft)	8-9	8-9	8-9	MR	NR	8-9	NR	4-6	NR	4-6	NR	NR	X	Soil
Date	7/13/98	7/13/98	7/13/98			7/12/98		7/12/98		7/12/98				Standards
		DIESEL T.	DIESEL TANK AREA					GAS	GASOLINE TANK AREA	NK AREA				
PARAMETER														
Gasoline Range Organics (ppm)	N/A	N/A	N/A	N/A	N/A	200	N/A	720	N/A	1,000	N/A	N/A	N/A	100
Diesel Range Organics (ppm)	20	<3.3	<3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	100
VOLATILE ORGANIC COMPOUNDS (ppb)	(ppp)													
Benzene	<25	<25	<25	N/A	N/A	< 100	N/A	<310	N/A	< 500	N/A	N/A	N/A	5.5
Ethylbenzene	<25	<25	<25	N/A	N/A	300	N/A	6500	N/A	2700	N/A	N/A	N/A	2900
Methyl-tert-butyl-ether	<25	<25	<25	N/A	N/A	< 100	N/A	<310	N/A	< 500	N/A	N/A	N/A	-
Toluene	<25	<25	<25	N/A	N/A	< 100	N/A	4500	N/A	5000	N/A	N/A	N/A	1500
1,2,4-&1,3,5 Trimethylbenzenes	<25	<25	<25	N/A	N/A	31,100	N/A	81,000	N/A	113,000	N/A	N/A	N/A	1
Total Xylenes	<25	<25	<25	N/A	N/A	12,700	N/A	000'69	N/A	103,000	N/A	N/A	N/A	4100
POLYNUCLEAR AROMATIC HYDROCARBONS (ppm)	ROCARBC	(mdd) SNo												
Acenaphthene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	38
Acenaphthylene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0.7
Anthracene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	3000
Benzo(a)anthracene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	17
Benzo(a)pyrene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	48
Benzo(b)fluoranthene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	360
Benzo(ghi)perylene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0089
Benzo(k)fluoranthene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	870
Chrysene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	37
Dibenzo(a,h)anthracene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	38
Fluoranthene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	500
Fluorene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	100
Indeno(1,2,3-cd)pyrene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	089
1- Methylnaphthalene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	23
2-Methylnaphthalene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	20
Naphthalene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0.4
Phenanthrene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	1.8
Pyrene	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	8700
METALS (ppb)											-			
Lead	N/A	N/A	N/A	N/A	N/A	<3400	N/A	<3500	N/A	<3400	N/A	N/A	N/A	50,000

N/A = Not Analyzed

--- = no value has been established

NR = Not Reported

< = number following the "<" symbol is the method detection limit

Shaded value exceeds standard for that parameter PAH standards are for groundwater pathway residual contaminant levels (RCL)



TABLE 4 (CONTINUED)

UNITED STATES POSTAL SERVICE - MADISON VEHICLE MAINTENANCE FACILITY PRE-REMEDIATION SOIL ANALYTICAL DATA

MADISON, WISCONSIN

MAXIM #9910623

Location	SB-14	SB-15	SB-16	SB-17	SB-18	61-8S	SB-20	SB-21	SB-23	SB-24	SB-25	SB-26	NR 700
Depth (ft)	4-6	NR	8-9	8-9	NR	8-10	8-9	8-9	8-9	X	4-6	8-9	Soil
Date	7/14/98		7/12/98	7/13/98		7/13/98	7/13/98	7/13/98	7/13/98		7/14/98	7/14/98	Standards
		GASOL	GASOLINE TANK	VK AREA			HYDRAULIC LIFT AREA	LIFT ARE	1	GAS	GASOLINE TANK AREA	NK AREA	
PARAMETER													
Gasoline Range Organics (ppm)	<2.6	NR	<2.6	<2.7	N/A	N/A	N/A	N/A	N/A	NR	<2.6	<2.7	100
Diesel Range Organics (ppm)	N/A	NR	N/A	N/A	N/A	7,700	9,200	7,100	<3.3	NR.	N/A	N/A	100
VOLATILE ORGANIC COMPOUNDS (ppb)	(ppb)											CANTANA NA CANTANA MANAGAMBANA	
Benzene	<25	NR	<25	<25	N/A	N/A	N/A	N/A	N/A	NR	<25	<25	5.5
Ethylbenzene	<25	NR	<25	<25	N/A	N/A	N/A	N/A	N/A	NR.	<25	<25	2900
Methyl-tert-butyl-ether	<25	NR	<25	<25	N/A	N/A	N/A	N/A	N/A	NR	<25	<25	
Toluene	<25	NR	<25	<25	N/A	N/A	N/A	N/A	N/A	NR.	<25	<25	1500
1,2,4-&1,3,5 Trimethylbenzenes	<25	NR	<25	<25	N/A	N/A	N/A	N/A	N/A	XX.	<25	<25	1
Total Xylenes	<25	NR	<25	<25	N/A	N/A	N/A	N/A	N/A	NR	<25	<25	4100
POLYNUCLEAR AROMATIC HYDROCARBONS (ppm)	ROCARBON	S (ppm)											
Acenaphthene	N/A	NR	N/A	N/A	N/A	<0.092	< 0.520	< 0.360	<0.052	NR	N/A	N/A	38
Acenaphthylene	N/A	NR	N/A	N/A	N/A	< 0.180	< 1.000	<0.730	< 0.100	NR	N/A	N/A	0.7
Anthracene	N/A	NR	N/A	N/A	N/A	<0.0037	< 0.021	< 0.015	< 0.0021	NR	N/A	N/A	3000
Benzo(a)anthracene	N/A	NR	N/A	N/A	N/A	< 0.018	< 0.026	< 0.018	<0.0026	NR.	N/A	N/A	17
Benzo(a)pyrene	N/A	NR	N/A	N/A	N/A	< 0.015	< 0.021	< 0.015	< 0.0021	NR	N/A	N/A	49
Benzo(b)fluoranthene	N/A	NR	N/A	N/A	N/A	< 0.015	< 0.021	< 0.015	< 0.0021	NR	N/A	N/A	360
Benzo(ghi)perylene	N/A	NR	N/A	N/A	N/A	< 0.022	< 0.062	< 0.065	< 0.0031	NR	N/A	N/A	0089
Benzo(k)fluoranthene	N/A	NR	N/A	N/A	N/A	< 0.015	< 0.021	< 0.015	< 0.0021	NR	N/A	N/A	028
Chrysene	N/A	NR	N/A	N/A	N/A	< 0.018	< 0.026	< 0.018	< 0.0026	NR	N/A	N/A	37
Dibenzo(a,h)anthracene	N/A	NR.	N/A	N/A	N/A	< 0.015	< 0.041	< 0.044	< 0.0021	NR	N/A	N/A	38
Fluoranthene	N/A	NR	N/A	N/A	N/A	< 0.0037	< 0.021	< 0.015	< 0.0021	NR	N/A	N/A	500
Fluorene	N/A	NR	N/A	N/A	N/A	< 0.018	< 0.100	< 0.073	< 0.010	NR	N/A	N/A	100
Indeno(1,2,3-cd)pyrene	N/A	NR	N/A	N/A	N/A	< 0.015	< 0.041	< 0.044	< 0.0021	NR	N/A	N/A	089
1 - Methylnaphthalene	N/A	NR	N/A	N/A	N/A	< 0.092	< 0.520	< 0.360	< 0.052	NR	N/A	N/A	23
2-Methylnaphthalene	N/A	NR	N/A	N/A	N/A	< 0.092	< 0.520	< 0.360	< 0.052	NR	N/A	N/A	20
Naphthalene	N/A	NR	N/A	N/A	N/A	< 0.092	< 0.520	< 0.360	< 0.052	NR	N/A	N/A	0.4
Phenanthrene	N/A	NR	N/A	N/A	N/A	< 0.018	< 0.100	< 0.073	< 0.010	NR	N/A	N/A	1.8
Pyrene	N/A	NR	N/A	N/A	N/A	< 0.018	< 0.100	< 0.073	< 0.010	NR.	N/A	N/A	8700
METALS (ppb)												MICHAEL MICHAEL MANAGER AND	
Lead	4700	NR	<3400	< 3400	N/A	N/A	N/A	N/A	N/A	NR	5300	< 3600	50,000

N/A = Not Analyzed

--- = no value has been established

NR = Not Reported

< = number following the "<" symbol is the method detection limit Shaded value exceeds standard for that parameter PAH standards are for groundwater pathway residual contaminant levels (RCLs)



TABLE 4 (CONTINUED) PRE-REMEDIATION SOIL ANALYTICAL DATA UNITED STATES POSTAL SERVICE MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM #9910623

Location	SB-22	Comm 46
Depth (ft)	2-4	Soil Standards
		For
Date	7/13/98	Direct Contact
PARAMETER	- I	I .
Gasoline Range Organics (ppm)	N/A	
Diesel Range Organics (ppm)	<3.4	
VOLATILE ORGANIC COMPOUNDS	(ppb)	
Benzene	N/A	1100
Ethylbenzene	N/A	400,000
Methyl-tert-butyl-ether	N/A	
Toluene	N/A	670,000
1,2,4-&1,3,5 Trimethylbenzenes	N/A	
Total Xylenes	N/A	470,000
POLYNUCLEAR AROMATIC HYDRO	OCARBONS (ppm)	
Acenaphthene	< 52	900
Acenaphthylene	< 100	18
Anthracene	<2.1	5000
Benzo(a)anthracene	< 2.6	0.088
Benzo(a)pyrene	<2.1	0.0088
Benzo(b)fluoranthene	<2.1	0.088
Benzo(ghi)perylene	< 3.1	1.8
Benzo(k)fluoranthene	<2.1	0.88
Chrysene	<2.6	8.8
Dibenzo(a,h)anthracene	<2.1	0.0088
Fluoranthene	<2.1	600
Fluorene	< 10	600
Indeno(1,2,3-cd)pyrene	<2.1	0.088
1- Methylnaphthalene	< 52	1100
2-Methylnaphthalene	< 52	600
Naphthalene	< 52	20
Phenanthrene	< 10	18
Pyrene	< 10	500
METALS (ppb)		
Lead	N/A	

N/A = Not Analyzed --- = no value established NR = Not Reported < = number following the "<" symbol is the method detection limit Shaded value exceeds standard for that parameter PAH standards are for Non-Industrial Direct Contact



TABLE 6 POST-REMEDIATION CHEMICAL ANALYSIS OF SOIL REMEDIAL EXCAVATION OF HYDRAULIC LIFT AREA UNITED STATES POSTAL SERVICE MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM #9910623

Boring	S-1	S-2	S-3	S-4	S-5	NR 720 Soil
Depth (ft bls)	9.5	9.5	9.5	9.5	9.5	Cleanup
Date Sampled	2/11/99	2/11/99	2/11/99	2/11/99	2/11/99	Standard
PARAMETER (mg/Kg)						
Diesel Range Organics	1.4	<1.3	4.5	51,000	1500	100*
Gasoline Range Organics						100*
PETROLEUM VOLATILE ORG	ANIC COM	POUNDS (P	VOC)	Wanter Commence of the Commenc		
Benzene	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005	0.0055
Toluene	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005	1.5
Ethylbenzene	< 0.006	< 0.006	< 0.006	< 0.006	< 0.006	2.9
Total Xylenes	< 0.008	< 0.008	< 0.008	< 0.008	< 0.008	4.1
1,2,4 & 1,3,5-Trimethylbenzenes	< 0.006	< 0.006	< 0.006	< 0.006	< 0.006	
MTBE	< 0.008	< 0.008	< 0.008	< 0.008	< 0.008	
POLYNUCLEAR AROMATIC I	IYDROCAR	BONS (PAH))			
Acenaphthene	< 0.019	< 0.019	< 0.019	0.075	< 0.019	38
Acenaphthylene	< 0.038	< 0.038	< 0.038	< 0.038	< 0.038	0.7
Anthracene	< 0.0017	< 0.0017	< 0.0017	0.064	< 0.0017	3000
Benzo(a)Anthracene	< 0.0019	< 0.0019	< 0.0019	0.140	0.130	17
Benzo(a)Pyrene	< 0.0027	< 0.0027	< 0.0027	0.040	0.0038	48
Benzo(b)Fluoranthene	0.0049	0.0048	< 0.0024	0.110	0.028	360
Benzo(k)Fluoranthene	< 0.0012	< 0.0012	< 0.0012	0.210	0.038	870
Benzo(ghi)Perylene	< 0.0039	< 0.0039	< 0.0039	0.060	0.052	6800
Chrysene	0.0039	< 0.0019	< 0.0019	0.440	0.078	37
Dibenzo(ah)Anthracene	< 0.0025	< 0.0025	< 0.0025	0.075	< 0.0025	38
Fluoranthene	< 0.0051	< 0.0051	< 0.0051	0.120	< 0.0051	600
Fluorene	< 0.0027	< 0.0027	< 0.0027	0.040	0.0039	100
Indeno(1,2,3-cd)Pyrene	< 0.0021	< 0.0021	< 0.0021	0.0076	0.022	680
1-Methyl Naphthalene	< 0.026	< 0.026	< 0.026	0.140	< 0.026	23
2-Methyl Naphthalene	< 0.023	< 0.023	< 0.023	0.270	< 0.023	20
Naphthalene	< 0.023	< 0.023	< 0.023	< 0.022	< 0.023	0.4
Phenanthrene	< 0.002	< 0.002	< 0.002	0.019	< 0.002	1.8
Pyrene	< 0.0028	< 0.0028	< 0.0028	0.120	0.0061	8700
METALS						
Cadmium	< 0.12	< 0.11	< 0.12	< 0.11	<0.11	NS
Zinc	5.19	15.3	5.52	4.97	4.97	NS

bls = below land surface

mg/Kg = milligrams per kilogram (parts-per-million)


NS = no soil standard currently applicable

= Parameter was not detected and if present is less than the limit of detection reported Shaded area indicates generic soil standard exceedance

PAH standards are for groundwater pathway Residual Contaminant Levels (RCL)

Locations of soil samples obtained from the remedial excavation are shown on Figures 10 and 11

^{* =} standard corresponds to permeable soils (hydraulic conductivity > 10 E-6 cm/s)



MAXIM TECHNOLOGIES, INC.®


TABLE 1 GROUNDWATER TABLE ELEVATION DATA UNITED STATES POSTAL SERVICE MADISON VEHICLE MAINTENANCE FACILITY MADISON, WISCONSIN MAXIM #9910623


					LOCA	TION				
DATE	MW-1	MW-2	MW-3	MW-4	MW-5	MW-6	MW-7	MW-8	MW-3P	RW-1R
7/26/95	91.91	91.85	91.51	91.56	91.74		,			
1/17/96	91.51	91.47	91.21	91.50	91.39	90.93	91.95	90.90		
4/25/96	91.78	91.55	91.52	91.72	91.69	91.27	91.29	91.20		
6/16/98	92.83	92.48	91.51	92.53		91.16	91.87	91.77	92.34	
7/14/98	***				93.05				92.34	Tel 04
1/17/99	91.55	91.21		91.28	91.42			*	91.18	
2/11/99			91.68			91.32	91.34	*		
7/16/99	93.99	93.66	93.67	93.62	93.87	93.25	93.39	*	93.60	
9/1/99	92.78	92.48	92.43	92.51	92.63	92.06	92.10	*	93.31	
11/16/99	92.80	92.44	92.46	92.37	92.67		92.27	90.26	92.51	
	REFEREN	CE ELEVAT	ION - TOP	PVC RISER	PIPE					•
	99.95	99.92	99.99	99.95	100.44	98.97	100.31	98.85	102.88	


Monitoring well locations are shown on Figure 2.


A groundwater contour map constructed from the most current water level data is provided in Figure 3. All elevations given in feet, relative to a benchmark set at 100 ft.

- -- = No data recorded
- * = Well not located









RP STATEMENT

HARD COPY ONLY

Re: GIS Package

USPS Madison VMF

201 Regas Rd.

Madison, Wisconsin

Commerce #53714-9999-01-A

R. WILLIAMS, hereby agree that the legal property descriptions (Print Name) attached to this document are complete and accurate to the best of my knowledge."

Allens, REM
Compliance Specialist



July 30, 2003

Gordy Voit Regas Company 3461 Milwaukee St. Madison, WI 53714 Via Certified Mail w/ return receipt

RE: US Postal Service VMF

201 Regas Road (3902 Milwaukee St.)

Madison, WI

Dear Property Owner:

"Groundwater contamination that appears to have originated on the property located at 201 Regas Road has migrated onto your property at 204 Regas Road. The levels of benzene contamination in the groundwater on your property are above the state groundwater enforcement standards found in chapter NR 140, Wisconsin Administrative Code. However, the environmental consultants who have investigated this contamination have informed me that this groundwater contaminant plume is stable or receding and will naturally degrade over time. I believe that allowing natural attenuation to complete the cleanup at this site will meet the requirements for case closure that are found in chapter NR 726 and chapter Comm 46 if this site is eligible for closure under Comm 46, Wisconsin Administrative Code, and I will be requesting that the Department of Commerce accept natural attenuation as the final remedy for this site and grant case closure. Closure means that the Department will not be requiring any further investigation or cleanup action to be taken, other than the reliance on natural attenuation." "Since the source of the groundwater contamination is not on your property, neither you nor any subsequent owner of your property will be held responsible for investigation or cleanup of this groundwater contamination, as long as you and any subsequent owners comply with the requirements of section 292.13, Wisconsin Statutes, including allowing access to your property for environmental investigation or cleanup if access is required. For further information on the requirements of section 292.13, Wisconsin Statutes, you may call 1-800-367-6076 for calls originating in Wisconsin, or 608-264-6020 if you are calling from out of state or within the Madison area, to obtain a copy of the Department of Natural Resources' publication #RR-589, Fact Sheet 10: Guidance for Dealing with Properties Affected by Off-Site Contamination." "The Department of Commerce will not review my closure request for at least 30 days after the date of this letter. As an affected property owner, you have a right to contact the Department to provide any technical information that you may have that indicates that closure should not be granted for this site. If you would like to submit any information to the Department of Commerce that is relevant to this closure request, you should mail that information to: Eric Scott, P.O.Box 8044, Madison, Wisconsin, 53707-8044."

"If this case is closed, all properties within the site boundaries where groundwater contamination exceeds chapter NR 140 groundwater enforcement standards will be listed on the Department of Natural Resources' geographic information system (GIS) Registry of Closed Remediation Sites. The information on the GIS Registry includes maps showing the location of properties in Wisconsin where groundwater contamination above chapter NR 140 enforcement standards was found at the time that the case was closed. This GIS Registry will be available to the general

Suite E-1500

St. Paul, Minnesota 55101

public on the Department of Natural Resources' internet web site. Please review the enclosed legal description of your property, and notify me within the next 30 days if the legal description is incorrect." "Should you or any subsequent property owner wish to construct or reconstruct a well on your property, special well construction standards may be necessary to protect the well from the residual groundwater contamination. Any well driller who proposes to construct a well on your property in the future will first need to call the Diggers Hotline (1-800-242-8511) if your property is located outside of the service area of a municipally owned water system, or contact the Drinking Water program within the Department of Natural Resources if your property is located within the designated service area of a municipally owned water system, to determine if there is a need for special well construction standards." "Once the Department makes a decision on my closure request, it will be documented in a letter. If the Department grants closure, you may obtain a copy of this letter by requesting a copy from me, by writing to the agency address given above or by accessing the DNR GIS Registry of Closed Remediation Sites on the internet at www.dnr.state.wi.us/org/at/et/geo/gwur. A copy of the closure letter is included as part of the site file on the GIS Registry of Closed Remediation Sites." "If you need more information, you may contact me at 651-227-6500, 332 Minnesota Street, Suite E-1500, St. Paul, MN, 55101 or you may contact Eric Scott, P.O.Box 8044, Madison, Wisconsin, 53707-8044 or at 608-266-8516."

Sincerely, NATS

Matt Schemmel, P.G.

Hydrogeologist

	STATE BAR OF FORM 3- QUIT CLAIM	1982	DANE COUNTY REGISTER OF DEEDS
DOCUMENT NO.	QUI CEAL		Doc No 2769244
Gordon G. Voit			1996-06-07 10:08 AM Trans. Fee EXEMPT #155 Rec. Fee 10.00 Pages 1
		("Grantor")	Waadaga 65
uit-claims to Regas Company	y, LLC, a Wisconsin I	imited liability	V33126P 65
ompany		("Grantee")	
the following described real estate in Dane County,			RETURN TO David B. Billing Solbeim Billing & Grimmer, S.C. P.O. Box 1644
State of Wisconsin:			Madison, WI 53701-1644
	Tau I	barcal No · 60-0	710-042-0086-3 & 60-0710-042-0091-2
line of said NW 1/4, 1,2 thence continuing N 7°- right-of-way line of Re feet; thence along the ar bears S 42°-10'-06" W, 87°-11'-30" W, along s This conveyance is exer This	267.45 feet; mence N27'-06" E, 359.87 feet; gas Road; thence S 2°- rc of a curve to the right, 35.37 feet to the north said north right-of-way, mpt from a transfer fee homestead property.	thence N 87°-14 51'-19" E, along whose radius is right-of-way lin 412.10 feet to th	87°-49°-41" E, along the South 3 feet to the point of beginning; 1°-47" E, 372.73 feet to the west 25.00 feet and whose long chord e of Milwaukee Street; thence S are point of beginning. 5. Stats. Section 77.25(15s).
Dated this day of		b 1 92	
	(SEAL)	francis of	
*		* Gordon G. Y	/oit
	(SEAL)		(SEAL)
	(SEAL)		
*		*	
AUTHENTIC	CATION	A	CKNOWLEDGMENT
Signature (s) of Gordon G. Vo	oit		SCONSIN)) ss. County)
authoriticated this 4 day of 19 96		Persona	ally came before me this day of, 19 the above named
1//3//			
David B. Billing	BAR OF WISCONSIN		
(If not,authorized by §706.06	, Wis. Stats.)		
THIS INSTRUMENT WAS DRAFTED BY			o be the person who executed the nument and acknowledge the same.
David B. Billing			
Solheim Billing & Grimme (Signatures may be authentic Both are not necessary.)	er. S.C. cated or acknowledged	* Notary Public My Commissi	County, Wis. on is permanent. (If not, state expiration, 19)
		date:	, 19)

STATE BAR OF WISCONSIN FORM No. 3-1982 Solheim Billing & Grimmer, S.C. (Rev. 9/95 DBB/lal)



July 30, 2003

Via Certified Mail w/ return receipt

City of Madison Engineering 210 Martin Luther King Jr. Blvd. **Room 115** Madison, WI 53703

RE:

US Postal Service VMF

201 Regas Road (3902 Milwaukee St.)

Madison, WI

Dear Property Owner:

"Groundwater contamination that appears to have originated on the property located at 201 Regas Road has migrated onto your property between 201 Regas Road and 204 Regas Road. The levels of benzene contamination in the groundwater on your property are above the state groundwater enforcement standards found in chapter NR 140, Wisconsin Administrative Code.

Groundwater contamination within the right-of-way are above the state groundwater enforcement standards found in chapter NR 140, Wisconsin Administrative Code. However, DPRA has completed an investigation and concluded that the groundwater contaminant plume is stable or receding and will naturally degrade over time. DPRA believes that allowing natural attenuation to complete the cleanup at this site will meet the requirements for case closure that are found in chapter NR 726 and chapter Comm 46, Wisconsin Administrative Code, and DPRA will be requesting that the WDNR accept natural attenuation as the final remedy for this site and grant case closure. Closure means that the Department will not be requiring any further investigation or cleanup action to be taken, other than the reliance on natural attenuation.

In order to receive site closure, notification is required for the local municipality which owns any right-of-way property which may be impacted by contamination. Groundwater sampling results indicate that petroleum constituents were present at concentrations above WDNR enforcement standards within the right-of-way.

"Since the source of the groundwater contamination is not on your property, neither you nor any subsequent owner of your property will be held responsible for investigation or cleanup of this groundwater contamination, as long as you and any subsequent owners comply with the requirements of section 292.13, Wisconsin Statutes, including allowing access to your property for environmental investigation or cleanup if access is required. For further information on the requirements of section 292.13, Wisconsin Statutes, you may call 1-800-367-6076 for calls originating in Wisconsin, or 608-264-6020 if you are calling from out of state or within the Madison area, to obtain a copy of the Department of Natural Resources' publication #RR-589, Fact Sheet 10: Guidance for Dealing with Properties Affected by Off-Site Contamination." "The Department of Commerce will not review my closure request for at least 30 days after the date of this letter. As an affected property owner, you have a right to contact the Department to provide any technical information that you may have that indicates that closure should not be granted for this site. If you would like to submit any information to the Department of Commerce that is

St. Paul Minnesota 55101

Telephone 651-227-6500

relevant to this closure request, you should mail that information to: Eric Scott, P.O.Box 8044, Madison, Wisconsin, 53707-8044."

"If this case is closed, all properties within the site boundaries where groundwater contamination exceeds chapter NR 140 groundwater enforcement standards will be listed on the Department of Natural Resources' geographic information system (GIS) Registry of Closed Remediation Sites. The information on the GIS Registry includes maps showing the location of properties in Wisconsin where groundwater contamination above chapter NR 140 enforcement standards was found at the time that the case was closed. This GIS Registry will be available to the general public on the Department of Natural Resources' internet web site. Please review the enclosed map of your property, and notify me within the next 30 days if the description is incorrect." "Should you or any subsequent property owner wish to construct or reconstruct a well on your property, special well construction standards may be necessary to protect the well from the residual groundwater contamination. Any well driller who proposes to construct a well on your property in the future will first need to call the Diggers Hotline (1-800-242-8511) if your property is located outside of the service area of a municipally owned water system, or contact the Drinking Water program within the Department of Natural Resources if your property is located within the designated service area of a municipally owned water system, to determine if there is a need for special well construction standards." "Once the Department makes a decision on my closure request, it will be documented in a letter. If the Department grants closure, you may obtain a copy of this letter by requesting a copy from me, by writing to the agency address given above or by accessing the DNR GIS Registry of Closed Remediation Sites on the internet at www.dnr.state.wi.us/org/at/et/geo/gwur. A copy of the closure letter is included as part of the site file on the GIS Registry of Closed Remediation Sites."

"If you need more information, you may contact me at 651-227-6500, 332 Minnesota Street, Suite E-1500, St. Paul, MN, 55101 or you may contact Eric Scott, P.O.Box 8044, Madison, Wisconsin, 53707-8044 or at 608-266-8516."

Sincerely,

Matt Schemmel, P.G.

Matt Sel

Hydrogeologist

Cc: GIS Registration Packet

DPRA File 5766.0023